



Polyurethane Protective Tape

Painting Instructions

Technical Bulletin

February 2011

3M™ Polyurethane Protective Tapes and Boots may be painted after application to achieve special color effects or to color match application surfaces.

Prior to painting, the 3M Tapes and Boots must be properly applied to a clean, smooth surface.


A. Painting Methods

Standard spray painting methods are recommended.

B. Preparation of the 3M Tape or Boot Surface for Painting

Light scuffing and/or solvent wiping the film surface prior to painting is recommended. The following procedures should be followed.

1. Scuff the 3M Tape or Boot surface with 3M™ Scotch-Brite™ General Purpose Pad 7447.
2. Saturate a clean cotton rag with acetone or isopropyl alcohol* and lightly wipe the 3M Tape surface.
3. Wipe surface dry with a lint-free cloth before the solvent evaporates from the surface.



C. Painting the Applied 3M Tape or Boot

Most high quality outdoor grade enamels, lacquers and polyurethane paints can be used.

1. When using single-part paint systems, you may paint directly over the applied 3M Tape or Boot without using the recommended primer system. Thin coatings are best for maximum resiliency-acrylic enamels, for example.
2. When using two-part paint systems, such as Military Spec two-part urethane paints, it is critical that the surface of the 3M Tape or Boot be primed with a polyamide cured, two-part epoxy primer such as those meeting Mil-P-23377.

D. Drying

The painted tape or boot may be air dried at room temperature or force cured. Force curing such as oven drying at temperatures above 150°F (66°C) is not recommended.

***Note:** When using solvents and other chemical products, extinguish all ignition sources, including pilot lights, and follow the manufacturer's precautions and directions for use. Consult local air quality regulations that may regulate or prohibit the use of surface preparation and cleaning materials based on solvent (VOC) content.

Technical Bulletin

3M™ Polyurethane Protective Tape – Painting Instructions

Safety and Regulatory

- 3M™ Polyurethane Protective Tape is **100%** solids and contains no hazardous air pollutants (HAPs), volatile organic components (VOCs). Respiratory protection is not required under normal use conditions.
- Polyurethane Protective Tape meets US Federal and California regulations for landfillable materials. The product is potentially recyclable.
- Packaging materials meet US Federal and California regulations for landfillable materials and are recyclable or reusable.
- This product is considered to be an article that does not release or otherwise result in exposure to a hazardous chemical under normal use conditions.

Precautionary Information

Refer to Product Label and Material Safety Data Sheet for health and safety information before using this product. For additional health and safety information, please visit www.3M.com/msds or call 1-800-364-3577 or (651) 737-6501.

For Additional Information

In the U.S., call toll free 1-800-235-2376, or fax 1-800-435-3082 or 651-737-2171. For U.S. Military, call 1-866-556-5714. If you are outside of the U.S., please contact your nearest 3M office or one of the following branches:

Australia 61-2-498-9711 tel 61-2-498-9710 fax	Austria 01-86686-298 tel 01-86686-229 fax	Brazil 55 19 3838-7876 tel 55 19 3838-6892 fax	Canada 800-410-6880 ext. 6018 tel 800-263-3489 fax
China 86-21-62753535 tel 86-21-62190698 fax	Denmark 45-43-480100 tel 45-43-968596 fax	France 0810-331-300 tel 30-31-6195 fax	Germany 02131-14-2344 tel 02131-14-3647 fax
Italy 02-7035-2177 tel 02-7035-2125 fax	Japan 03-3709-8245 tel 03-3709-8743 fax	Korea 02-3771-4114 tel 02-786-7429 fax	Netherlands 31-71-5-450-272 tel 31-71-5-450-280 fax
South Africa 11-922-9111 tel 11-922-2116 fax	Spain 34-91-321-6000 tel 34-91-321-6002 fax	Switzerland 01-724-9114 tel 01-724-9068 fax	United Kingdom (0) 161-237-6174 tel (0) 161-237-3371 fax

Technical Information

The technical information, recommendations and other statements contained in this document are based upon tests or experience that 3M believes are reliable, but the accuracy or completeness of such information is not guaranteed.

Product Use

Many factors beyond 3M's control and uniquely within user's knowledge and control can affect the use and performance of a 3M product in a particular application. Given the variety of factors that can affect the use and performance of a 3M product, user is solely responsible for evaluating the 3M product and determining whether it is fit for a particular purpose and suitable for user's method of application.

Warranty, Limited Remedy, and Disclaimer

Unless an additional warranty is specifically stated on the applicable 3M product packaging or product literature, 3M warrants that each 3M product meets the applicable 3M product specification at the time 3M ships the product. 3M MAKES NO OTHER WARRANTIES OR CONDITIONS, EXPRESS OR IMPLIED, INCLUDING, BUT NOT LIMITED TO, ANY IMPLIED WARRANTY OR CONDITION OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE OR ANY IMPLIED WARRANTY OR CONDITION ARISING OUT OF A COURSE OF DEALING, CUSTOM OR USAGE OF TRADE. If the 3M product does not conform to this warranty, then the sole and exclusive remedy is, at 3M's option, replacement of the 3M product or refund of the purchase price.

Limitation of Liability

Except where prohibited by law, 3M will not be liable for any loss or damage arising from the 3M product, whether direct, indirect, special, incidental or consequential, regardless of the legal theory asserted, including warranty, contract, negligence or strict liability.

These products were manufactured under a 3M Quality Management System registered to the AS9100 standard.



Aerospace and Aircraft Maintenance Department

3M Center, Building 223-1N-14
St. Paul, MN 55144-1000
1-800-235-2376
www.3M.com/aerospace

3M and Scotch-Brite are trademarks
of 3M Company.

Please recycle. Printed in U.S.A.
©3M 2011 (2/11) All rights reserved.
60-0702-6358-0